





ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet












FIG.4B

